



Union Depot: Assessment of Historic Concrete and Timber Pile Structures

Arne JOHNSON

Principal

Wiss, Janney, Elstner
Associates, Inc.

Northbrook, IL, USA
ajohnson@wje.com



Kevin MICHOLS

Principal

Wiss, Janney, Elstner
Associates, Inc.

Northbrook, IL, USA
kmichols@wje.com



Summary

Rehabilitation of the historic Union Depot railroad terminal in St. Paul, Minnesota, USA hinged on whether the 90-year-old structure, which exhibited widespread and locally severe deterioration, had sufficient remaining capacity or could be effectively and practically repaired to support the anticipated loads of the rehabilitated facility. The unique approach used to assess the concrete superstructure and timber pile foundations of this very large facility, which relied on comprehensive field inspections followed by targeted testing and structural analysis, allowed most of the original structure to be salvaged and effectively repaired for the desired service life of 50 years.

Keywords: Historic structure, timber piles, wood decay, settlement, load testing, statistical analysis, concrete repair, hydrodemolition, shotcrete, cathodic protection, galvanic anodes, column jackets

1. The Union Depot

The historic Union Depot railroad terminal (Figure 1), constructed circa 1925 along the Mississippi River in St. Paul, Minnesota, USA, was a very active train station through the mid-1960s. In the 1970s, the Depot was converted into a postal distribution center, and most of the railroad tracks, platforms, and ballast were replaced with soil fill and paving. In 2009, Ramsey County Regional



Figure 1. Historic photograph of Union Depot, looking north, provided by Ramsey County Historical Society

Railroad Authority acquired the Depot and embarked on a \$130 million rehabilitation of the facility into a multi-modal transportation hub.

The Depot's sprawling track deck includes approximately six hundred 21-foot-square bays of reinforced concrete superstructure, with 21-inch thick, reinforced concrete slabs spanning between circular concrete columns and perimeter walls. The columns and walls are, in turn, supported on below-grade concrete pile caps and approximately 9,000 untreated timber piles.

Approximately 90 years of exposure to a harsh northern climate had taken their toll on the track deck superstructure. The concrete elements exhibited advanced deterioration due to leakage, age, and exposure. Loss of timber pile integrity was also suspected because of obvious signs of settlement and structural cracking in several areas of the track deck. Feasibility of the rehabilitation hinged on whether the existing structure had sufficient remaining capacity, or could be effectively and practically repaired, to reliably support the anticipated loads of the rehabilitated Depot.

of pile degradation, strategically located test pits (Figure 2) and direct examination of 54 piles, field and laboratory load testing of full pile sections (both intact and partially cut), and innovative statistical analysis to predict future reliability of the timber pile group.



Figure 2. Test pit with exposed pile caps and timber piles

It was concluded that the timber pile foundations supporting the southern portion of the track deck should not be relied upon to support the heavy rail loads proposed for that portion of the facility.

Underpinning or foundation replacement were recommended for that area. For the northern two-thirds of the track deck, where the pile conditions were better and the loads lighter, it was concluded that the existing foundations should have sufficient capacity to support the anticipated load and vehicle loads for the next 50 years, although there is a relatively low risk of localized foundation settlement that may need to be remedied should it occur.

Assessment of Concrete Superstructure

The concrete superstructure was assessed through a combination of field observations, laboratory testing, and structural analysis. The concrete superstructure exhibited significant deterioration (Figure 3) in varying degrees, including cracks, delaminations and spalling, exposed and corroded reinforcing steel, water leakage, cyclic freezing and thawing, and corrosion from deicing salts were identified as the primary causes of deterioration.

A comprehensive rehabilitation program that included partial depth and localized full-depth repairs, galvanic cathodic protection for corrosion mitigation, new deck waterproofing, and improved deck drainage was developed to restore deteriorated areas and enhance long-term durability to meet the desired 50-year service life extension.



Figure 3. Efflorescence, leakage and deterioration of concrete along construction joint in track deck

Current Status

The rehabilitation of Union Depot is scheduled for completion by December 2012. In the southern portion of the track deck, the majority of the deck and foundations were demolished and reconstructed to restore the original historic appearance; at select locations where deck replacement was deemed not feasible, the existing piles were underpinned. In the northern two-thirds of the track deck, the existing concrete deck and columns were retained and repaired, and the existing timber pile foundations were underpinned with concrete piles. The